

Screen Melt Support Struts

USING SCREEN MELT SUPPORT STRUTS

1. Place metal mold ring on kiln shelf.
2. Place kiln posts outside mold ring as shown.
3. Place support struts bridging between kiln posts with prongs inside kiln posts.
4. Place screen on support struts.

